

## 3527

Single Banjo Bolts, Male BSPP and Metric Thread

Nickel-plated brass, NBR



Scan for more dimensions



| C      | References  |
|--------|-------------|
| M5x0.8 | 3527 00 19* |
| G1/8   | 3527 00 10  |
| G1/4   | 3527 00 13  |
| G3/8   | 3527 00 17  |

\* With screwdriver slot

## 3529

Stacking Banjo for 3 Body High Modules, Male BSPP Thread

Nickel-plated brass, NBR



Scan for more dimensions



| C    | References |
|------|------------|
| G1/8 | 3529 00 10 |
| G1/4 | 3529 00 13 |
| G3/8 | 3529 00 17 |

## 3524

Threaded Banjo Bolts, Male/Female BSPP

Nickel-plated brass, NBR



Scan for more dimensions



| C    | References |
|------|------------|
| G1/8 | 3524 00 10 |
| G1/4 | 3524 00 13 |
| G3/8 | 3524 00 17 |
| G1/2 | 3524 00 21 |

## 3528

Stacking Banjo for 2 Body High Modules, Male BSPP and Metric Thread

Nickel-plated brass, NBR



Scan for more dimensions



| C      | References  |
|--------|-------------|
| M5x0.8 | 3528 00 19* |
| G1/8   | 3528 00 10  |
| G1/4   | 3528 00 13  |
| G3/8   | 3528 00 17  |

\* With screwdriver slot

### Installation Guide

1. Remove the O-ring
2. Insert the banjo body with the chamfer oriented upwards (see detail view)
3. Reinstall the O-ring



## Legris LF 3000® Oscillating Fittings

### 3159

Oscillating Elbow, Male BSPT Thread

Technical polymer, Nickel-plated brass, NBR



Scan for more dimensions



| ØD | C    | References |
|----|------|------------|
| 4  | R1/8 | 3159 04 10 |
| 6  | R1/8 | 3159 06 10 |
|    | R1/4 | 3159 06 13 |
|    | R1/8 | 3159 08 10 |
| 8  | R1/4 | 3159 08 13 |
|    | R3/8 | 3159 08 17 |
| 10 | R1/4 | 3159 10 13 |
|    | R3/8 | 3159 10 17 |
| 12 | R1/4 | 3159 12 13 |
|    | R3/8 | 3159 12 17 |

Pre-coated thread

### 3189

Oscillating Elbow, Male BSPP and Metric Thread

Technical polymer, Nickel-plated brass, NBR



Scan for more dimensions



| ØD | C      | References |
|----|--------|------------|
| 4  | M5x0.8 | 3189 04 19 |
|    | G1/8   | 3189 04 10 |
|    | M5x0.8 | 3189 06 19 |
| 6  | G1/8   | 3189 06 10 |
|    | G1/4   | 3189 06 13 |
|    | G1/8   | 3189 08 10 |
| 8  | G1/4   | 3189 08 13 |
|    | G3/8   | 3189 08 17 |
| 10 | G1/4   | 3189 10 13 |
|    | G3/8   | 3189 10 17 |
| 12 | G1/4   | 3189 12 13 |
|    | G3/8   | 3189 12 17 |

## Legris LF 3000® Self-Sealing Fittings

### 3091

Self-Sealing Stud Fitting, Male BSPT Thread

Nickel-plated brass, NBR



Scan for more dimensions



| ØD | C    | References |
|----|------|------------|
| 4  | R1/8 | 3091 04 10 |
| 6  | R1/8 | 3091 06 10 |
|    | R1/8 | 3091 08 10 |
| 8  | R1/4 | 3091 08 13 |

Maximum operating pressure: 10 bar.

### 3160

Self-Sealing Plug-In Fitting

Technical polymer, NBR



Scan for more dimensions



| ØD | References |
|----|------------|
| 4  | 3160 04 00 |
| 6  | 3160 06 00 |
| 8  | 3160 08 00 |

Maximum operating pressure: 10 bar.

### 3391

Self-Sealing Stud Fitting, Male BSPP Thread

Nickel-plated brass, NBR



Scan for more dimensions



| ØD | C    | References |
|----|------|------------|
| 4  | G1/8 | 3391 04 10 |
| 6  | G1/8 | 3391 06 10 |
| 8  | G1/8 | 3391 08 10 |
|    | G1/4 | 3391 08 13 |
| 10 | G3/8 | 3391 10 17 |

Maximum operating pressure: 10 bar.